


Parallel inductor



2 inductor values

To VD909S road sensor

Two VD909S sensors may be wired into the same module. Each sensor would then have half the sensitivity it would have had on the module on its own.

There are no adjustments on the module. Additional inductors may be added to the loop input to reduce a sensor's sensitivity.

The pack contains one marked 101K or 104C or 151K or 154C and another marked 470K or 473C. The sensitivity adjustment follows the table below.

<u>Inductor</u>	<u>Sensitivity reduction</u>	
Neither		Full
470K or 473C	White	33%
101K or 104C	Blue	50%
151K or 154C	Red	60%
Both inductors		70%

A sensor with no inductors is sensitivity is max.